

#### Preventing Accidents in Biogas Plants - Experience of an Expert Witness for Biogas Plants -

Torsten Fischer and Dr Katharina Backes

Krieg & Fischer Ingenieure GmbH Bertha-von-Suttner-Straße 9, D-37085 Göttingen, Germany Tel.: ++49 551 900 363-0, Fax: ++49 551 900 363-29 Fischer@KriegFischer.de www.KriegFischer.de

> London, Ontario March 10, 2010

#### Krieg & Fischer Ingenieure GmbH



Engineering Office, specialized in Design and Engineering of Biogas Plants

- Foundation: 1999
- Team: 18
- Experience: > 20 Years
- References: ca. 140 Biogas Plants
- in: Germany, Japan, Netherlands, Austria, Switzerland, Lithuania, Italy, Slovakia, Canada, USA, Spain, France, Ireland
- Partner: Japan, Korea, USA, Canada, Bulgaria, France, Hungary, Turkey, Poland, Italy Spain, Ireland, Serbia







#### **Torsten Fischer**

• President of Krieg & Fischer Ingenieure GmbH

→ founded by Andreas Krieg



and Torsten Fischer in 1999

- Education: Engineer for Shipbuilding Construction
- Experience in the field of biogas since 1992
- → special fields: waste management and municipal engineering
   safety aspects of biogas plants
- Lecturer at Universities of Höxter and Gießen
- Accreditation of the Chamber of Engineers of Germany as Expert Witness in the field of biogas



#### **References - Examples**





**Central Biogas Plant** 



**Energy Crop Biogas Plant** 



**Kitchen Waste Digestion** 





Potato Residue Digestion



**Energy Crops with Cattle Manure** 



**Biowaste Digestion** 

Experience of an insurance company



Damages at different parts of the plant - payments related to different plant parts





Additional damages - Digester Tanks-



#### Part of financial Losses in Digester Damages



**Speaker: Torsten Fischer** 

Contracts starting 2005

Contracts up to 2005

Krieg & Fischer Ingenieure GmbH

6/29

March 10, 2010



#### Experience of Gothaer Insurance Company



- → more than 50% of all damages cause payments of less than € 10,000
- → payments of damages above € 50,000 are paid at 5% of all damages



Experience of Gothaer Insurance Company

- different quality of the plants
  - plant construction
  - operation
- about 80% of the insurance contracts are damagefree (lots of new plants still have warranty)



#### Experience of Gothaer Insurance Company



# Number of Damages increase disproportionate to Age of Plant

Krieg & Fischer Ingenieure GmbH Speaker: Torsten Fischer









The CHP-Container had a Timber Flooring.

**Krieg & Fischer Ingenieure GmbH** 

**Speaker: Torsten Fischer** 

March 10, 2010

11/29







Floor was contaminated with Oil Residues and Lube Oil.







Hot Exhaust Pipe was set up with little Distance to Timber Flooring.

→ Timber Flooring dried
 up
 → Dried Timber Flooring
 ignited and carbonized





Caused by increasing Temperature the Plastics of the Cable Insulation and Holders melted and dripped off.

**Krieg & Fischer Ingenieure GmbH** 





Melted Plastic dropped down on PE-Biogas Pipe underneath Container.

- $\rightarrow$  Pipe melted
- $\rightarrow$  causing Holes in Biogas Pipe



Krieg & Fischer Ingenieure GmbH

**Speaker: Torsten Fischer** 

March 10, 2010

16/29







Operator closed the wrong Biogas Valve

→Biogas still escaped overnight from Hole in the Pipe

**Krieg & Fischer Ingenieure GmbH** 



- Province-specified fire-protection regulations were not paid attention to
- Technical inadequateness:
  - exhaust pipe did not keep the required distance (to the timber flooring and to the cables)
  - exhaust pipe was not insulated against the timber flooring
  - biogas pipe below the container was not covered with soil
- The operator did not detect the reason



Conclusion:

- The damage has been categorized as extensive.
- The CHP-container has not been set up according to the actual regulations (province-specified fire- protection regulations are valid)
- No concerns have been expressed by the CHP provider
- Will the insurance pay the damage costs?



Krieg & Fischer received an E-Mail from the insurance company:

- Damage of a concrete Tank
- Which Tank was not noticeable from the Documentation of the Insurance Company
- Insurance Company asked for an Examination of the Documentation available on site the Biogas Plant



Data were only rudimental

- No Documentation
- No Flow-Sheet
- Site Layout was taken from Permission Documents and obsolete because the concrete tank was erected 2 years later

# → The new tank was not registered by the insurance company.





Screw pump

#### **Concrete Tank**

 Krieg & Fischer Ingenieure GmbH
 Speaker: Torsten Fischer
 March 10, 2010
 22/29





- Construction: 2005/2006
- Input: Energy Crops
- CHP: 536 kW<sub>e</sub>







The screw pump was not equipped with a pressure sensor on the pressure side of the pump or a protection against dry running.  $\rightarrow$  The pump could only be stopped manually.

24/29





If the maximum filling level of the tank is reached a warning massage is sent to the cell phone of the operator. He switches off the pump manually.





At the day of the accident the operator forgot his cell phone. The pump continued pumping manure into the tank...





...until the cover of the hydrolysis tank had been pushed up by the fluid pressure and blasted from the tank.

Krieg & Fischer Ingenieure GmbH Speaker: Torsten Fischer

March 10, 2010

27/29





- No documentation of the plant
- No process flow sheet
- Hydrolysis tank had been enhanced and equipped with a cover by the operator
- no structural calculation of the tank
- no safety-regulated documentation

#### Will the insurance company pay for a damaged tank they do not know about?



#### Preventing Accidents in Biogas Plants - Experience of an Expert Witness for Biogas Plants -

Torsten Fischer and Dr Katharina Backes

Krieg & Fischer Ingenieure GmbH Bertha-von-Suttner-Straße 9, D-37085 Göttingen, Germany Tel.: ++49 551 900 363-0, Fax: ++49 551 900 363-29 Fischer@KriegFischer.de www.KriegFischer.de

> London, Ontario March 10, 2010

# Study published by Federal Government of Germany





Mittlerer Anteil der einzelnen Störungen am Gesamtarbeitsaufwand zur Störungs, seitigung und rel. Häufigftretens der einzelnen Störungen